INFORMATION SHEET

WASTE DISCHARGER REQUIREMENTS ORDER NO.______
POST-CLOSURE MAINTENANCE AND MONITORING
COVE CONTRACTORS LANDFILL
SAN JOAQUIN COUNTY

Cove Contractors, Inc. and El Dorado Property Management, Inc. (Discharger) own the Cove Contractors, Incorporated landfill. The landfill is an unlined and unclassified landfill that was developed in a 21-acre abandoned clay pit. The southeastern 10-acres was mined from 1910 to 1955 and the clay was used in brick making operations. The brick manufacturing ceased in 1955; however, the quarrying for clay continued until 1967. After 1955, the Discharger began backfilling the clay quarry pit with dirt and broken concrete from construction contractors. Later on, the landfill started accepting auto shredder waste. This waste is in a 9-acre portion of the landfill. Discharge to the facility ceased in 1988. The facility is located at 3200 and 3242 South El Dorado Street, in Stockton, San Joaquin County.

The Discharger submitted Revised Landfill Closure and Post-Closure Maintenance Plans for the facility in January 2006 under Cleanup and Abatement Order No. R5-2006-0707. Regional Water Board staff approved the revised plans on 26 February 2006. The final cover is scheduled for completion in July 2007, in accordance with the approved closure plans. Closure includes a cover comprised of a two-foot thick foundation layer, a one-foot thick clay barrier layer, and a one-foot thick vegetative layer.

These Waste Discharge Requirements address post-closure maintenance and monitoring of the landfill.

There are seven groundwater monitoring wells in detection and corrective action monitoring (MW-2A, MW-3A, MW-5, MW-6, MW-7, MW-8, and MW-9A) due to historical inorganics exceeding water quality goals (metals, TDS, minerals, and conductivity), and organic detections (total petroleum hydrocarbon, polychlorinated biphenyls, and VOCs) in groundwater.

Site drainage is to Duck Creek, a tributary to Walker Slough, which flows into San Joaquin River Delta.

MLB: 5/25/2007